MAINTENANCE INFORMATION

SERIES 700 DOUBLE HUNG WINDOW

THE THERMAL WINDOW, INC. SERIES 700 DOUBLE HUNG WINDOW REQUIRES VERY LITTLE MAINTENANCE OR CARE FOR PROPER OPERATION.

WE RECOMMEND FOLLOWING THE INSTRUCTION OF AAMA PUBLICATIONS FOR CLEANING AND MAINTENANCE OF THE FINISH OF THE WINDOWS. SEE THE VOLUNTARY GUIDE SPECIFICATION THAT PERTAINS TO THE FINISH OF THE WINDOWS PROVIDED.

DUE TO THE OPERATING STYLE OF THE DOUBLE HUNG WINDOW THERE ARE A FEW SPEPS THAT MUST BE TAKEN IN ORDER TO INSURE CONSISTENT OPERATING PERFORMANCE.

- 1. THE TRACKS MUST REMAIN FREE OF OBSTRUCTIONS.
- 2. THE WINDOW MUST REMAIN IN A LEVEL AND PLUMB CONDITION.
- 3.THE BALANCES MUST BE CHECKED PERIODICALLY TO INSURE PROPER FUNCTION.

WE ARE CERTAIN THAT THE WINDOWS WILL OFFER EXCELLENT PERFORMANCE IF THE ABOVE PRECATUIO\NS ARE TAKEN.

SHOULD YOU REQUIRE ADDITIONAL INFORMATION OR IF YOU EXPERIENCE PROBLEMS WITH OUR PRODUCT PLEASE CONTACT:

THERMAL WINDOWS, INC. CONTRACT DEPARTMENT 12805 EAST 31st STREET TULSA, OK 74146-2310 1-800-259-7580 PHONE (918) 665-2197 FAX

THANK YOU.