

MAINTENANCE INFORMATION

SERIES 725 HORIZONTAL ROLLING WINDOW

THE THERMAL WINDOW, INC. SERIES 725 HORIZONTAL ROLLING WINDOW REQUIRES VERY LITTLE MAINTENANCE OR CARE FOR PROPER OPERATION.

WE RECOMMEND FOLLOWING THE INSTRUCTION OF AAMA PUBLICATIONS FOR CLEANING AND MAINTENANCE OF THE FINISH OF THE WINDOWS. SEE THE VOLUNTARY GUIDE SPECIFICATION THAT PERTAINS TO THE FINISH OF THE WINDOWS PROVIDED.

DUE TO THE OPERATING SYTLE OF THE HORIZONTAL ROLLING WINDOW THERE ARE A FEW STEPS THAT MUST BE TAKEN IN ORDER TO INSURE CONSISTENT OPERATING PERFORMANCE.

- 1. THE TRACKS MUST REMAIN FREE OF OBSTRUCTIONS.*
- 2. THE WINDOW MUST REMAIN IN A LEVEL AND PLUMB CONDITION.*
- 3. THE ROLLERS MUST BE CHECKED PERIODICALLY TO INSURE PROPER FUNCTION.*

WE ARE CERTAIN THAT THE WINDOWS WILL OFFER EXCELLENT PERFORMANCE IF THE ABOVE PRECAUTIONS ARE TAKEN.

SHOULD YOU REQUIRE ADDITIONAL INFORMATION OR IF YOU EXPERIENCE PROBLEMS WITH OUR PRODUCT PLEASE CONTACT:

THERMAL WINDOWS, INC.
CONTRACT DEPARTMENT
12805 EAST 31ST STREET
TULSA, OK 74146-2310
1-800-259-7580 PHONE
(918) 665-2197 FAX

THANK YOU.