

MAINTENANCE INFORMATION

SERIES 925 PROJECT OUT BOTTOM WINDOW

THE THERMAL WINDOW, INC. SERIES 925 PROJECT OUT BOTTOM WINDOW REQUIRES VERY LITTLE MAINTENANCE OR CARE FOR PROPER OPERATION.

WE RECOMMEND FOLLOWING THE INSTRUCTION OF AAMA PUBLICATIONS FOR CLEANING AND MAINTENANCE OF THE FINISH OF THE WINDOWS. SEE THE VOLUNTARY GUIDE SPECIFICATION THAT PERTAINS TO THE FINISH OF THE WINDOWS PROVIDED.

DUE TO THE OPERATING SYTLE OF THE PROJECT OUT BOTTOM WINDOW THERE ARE A FEW STEPS THAT MUST BE TAKEN IN ORDER TO INSURE CONSISTENT OPERATING PERFORMANCE.

- 1. THE FRAME MUST REMAIN FREE OF OBSTRUCTIONS.*
- 2. THE WINDOW MUST REMAIN IN A LEVEL AND PLUMB CONDITION*
- 3. THE ROTOR OPERATORS MUST BE CHECKED PERIODICALLY TO INSURE PROPER FUNCTION.*
- 4. HINGES AND LOCKING HANDLE(S) SHOULD BE CHECKED PERIODICALLY FOR DAMAGE OR OBSTRUCTIONS.*

WE ARE CERTAIN THAT THE WINDOWS WILL OFFER EXCELLENT PERFORMANCE IF THE ABOVE PRECAUTIONS ARE TAKEN.

SHOULD YOU REQUIRE ADDITIONAL INFORMATION OR IF YOU EXPERIENCE PROBLEMS WITH OUR PRODUCT PLEASE CONTACT:

THERMAL WINDOWS, INC.
CONTRACT DEPARTMENT
12805 EAST 31ST STREET
TULSA, OK 74146-2310
1-800-259-7580 PHONE
(918) 665-2197 FAX

THANK YOU.